GSE Model 675

Precision Counting Scale

USERS GUIDE

Version 2.0

SPX GSE scale systems

TABLE OF CONTENTS

CHAPTER 1: REFERENCE 1

KEYPAD FUNCTIONS 1
BACK PANEL CONNECTIONS 2

CHAPTER 2: CONFIGURATION 4

F1 SOFT KEY- QUICK COUNT 4
F2 SOFT KEY- GSE CUSTOM 5
Apw Lookup 5
F3 SOFT KEY- GSE DEFAULT 6
QUICK COUNT CONFIGURATION SETUP MENU 7
Setup 7
Setup Menus 8
CAL (Calibration) 8
Display Style 8
Preset Printouts 9
APW LOOKUP CONFIGURATION SETUP MENU 10
Setup 11
Setup Menus 11
CAL (Calibration) 11
Display Style 12
Print Menu 13
Preset Printouts 14
Advanced Setup Menu 15
Time/Date 16
Setup Mode Access (Setup) 16

CHAPTER 3: OPERATION 17

QUICK COUNT 17
Without Auto Tare 18
APW LOOKUP 19
Sample and Count 19
Without Auto Tare 19
Store a New Part Number 20
Update a Part Number 20
Recall a Part Number 20
Delete a Part Number 21
SIMPLE KEYPAD SAMPLE 21
Without Auto Tare 22

CHAPTER 4: CALIBRATION 23

CALIBRATION METHODS 23
General Notes on Calibration 23
New Zero 24

Last Zero 25
Temporary Zero 26
Only Zero 27
Calibration Reset 27
Known Loadcell Output 28
Multi - Scale Calibration 29

CHAPTER 5: LEGAL FOR TRADE 30

NTEP REQUIREMENTS 30
NTEP Custom Setup 31
Accessing the Custom Setup List 31
Custom Setup Parameters 31
Additional Conformance Considerations 32
SEALING AND AUDIT TRAILS 32
Physical Seal 33
Audit Trails 33
OIML Audit Trail 34
Calibration Audit Trail 34
Setup Audit Trail 34
Viewing Audit Trail Parameters 34
OMIL REQUIREMENTS 34
Enabling OIML Operation 35
OTHER REQUIREMENTS 35

CHAPTER 6: TROUBLESHOOTING 36

OPERATIONAL ERRORS 36
SETUP MODE ERRORS 36
HARDWARE ERRORS 37
CALIBRATION ERRORS 38
COMMUNICATION ERRORS 38

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:
https://the-checkout-tech.com/manuals/GSE/675 user and calibration v2 manual.html

And our free Online Keysheet maker:
https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/

HTTPS://THE-CHECKOUT-TECH.COM