WEIGH-TRONIX®

MODEL 600 FARM INDICATOR
User Instructions

NOT LEGAL FOR TRADE

ON

188880

SETUP

OFF

ZERO

PRINT
SELECT

WEIGH-TRONIX®

SERIAL NO

FAIRMONT, MINNESOTA U.S.A.

MODEL 600

Figure 1: Front Panel of Model 600 Farm Indicator

Key Functions

ON Pressed to power-on the indicator.
OFF Pressed to remove power.
ZERO Pressed to zero-balance the scale.
SETUP Pressed to scroll through three filtering options: lowest, medium, and highest filtering capabilities.

PRINT SELECT 1. Pressed in conjunction with the **SETUP** key to select the appropriate filtering option. 2. Pressed to capture and lock in on a weight reading and transmit the reading to a printer or other data-receiving device.

This is a "Table of Contents preview" for quality assurance

The full manual can be purchased from our store:
https://the-checkout-tech.com/manuals/Weigh-Tronix/600 operators manual.html

And our free Online Keysheet maker:
https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/

HTTPS://THE-CHECKOUT-TECH.COM