STAVELEY
WEIGHING & SYSTEMS GROUP

WEIGH-TRONIX

Model WI-120 Indicator User's Manual

TABLE OF CONTENTS

PART 1: INTRODUCTION TO THE WI-120 INDICATOR 1

DEFINITION AND OVERVIEW 1

SPECIFICATIONS FOR THE WI-120 INDICATOR 1

ENCLOSURES 2

FEATURES 3

System Support Features 3

Features Selectable Through Configuration Mode 3

Peripheral Printer or Computer Support Features 3

Optional Features 4

FRONT PANEL KEYBOARD FUNCTIONS 4

Keyboard Summary 4

Alphabetical Glossary of Key Functions 5

DISPLAY MESSAGES 6

PART II: OPERATING THE WI-120 INDICATOR 9

INITIAL OPERATING PROCEDURES 9

Setting the Operating Voltage 9

Powering-Up and Initializing 10

Accessing Configuration Mode and Viewing the Parameters 11

Applying Security Code for Tare and Cutoff Registers 13

Reading and Setting Time and Date 14

Enabling and Entering Identification Number 16

WEIGHING FUNCTIONS 17

Zeroing the Scale 17

Obtaining a Gross Weight Value 18

Using Pushbutton Tare Function to Store Container Weights 18

Using Keypad Multiple Tare Function to Store Container Weights 19

Entering Setpoints for Over/Under Indication 23

Entering Cutoff Values for Automated Scale Systems 24

Transmitting Data to Peripheral Devices 27

continued . . .

PART III: CONFIGURING THE WI-120 INDICATOR 29

PLANNING PERIPHERAL DEVICES FOR TRANSMISSION OF DATA 29

ENABLING CONFIGURATION MODE 31

SELECTING OPTIONS FOR FUNCTION PARAMETERS 32

Security Code 33
Time/Date 35
Units of Measure 37
Scale Capacity Multiplier 38
Decimal Point Placement 38
Division Size 39
Display Rate 39
Digital Motion Stabilizer (DMS) 40
Blank Display During Motion 41
Digital or Analog Zero 41
Automatic Zero Tracking (AZT) 42
Motion Send Window 42
Auto-Send After Motion 43
USA or Canadian Compliance 44
Power-Up Display 45
Identification Number 45
BCD Error Message 46
BCD Computer Interface with or without Data-Inhibit Signal 47

Serial Communication Parameters for Printer Port A 48

Port A: Printer Control Codes Parameter 50

Page-Formatting Parameters for Printer Port A 57

Serial Communication Parameters for Computer / Programmable Controller Port B 62

Formatting Parameters for Computer / Programmable Controller Port B 65

LOCKING IN SELECTIONS AND DISABLING CONFIGURATION 67

Appendix A: Addendum to the WI-120 Indicator User's Manual 68

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:
https://the-checkout-tech.com/manuals/Weigh-Tronix/WI-120 user manual.html

And our free Online Keysheet maker:
https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/

HTTPS://THE-CHECKOUT-TECH.COM