## QT-6100

## **Touch Screen Smart Terminal**

## Installation & Down Recovery Manual

Version 1.0 June 2008



1. System in	stallation	I-4
1-1.How to le	oad IPL (Initial Program Loading)	I-4
1-1-1. 1-1-2. 1-2.How to i	From PC to a terminal via RS-232C From CF card to a terminal nstall the system	I-5
1-2-1. 1-2-2. 1-2-3. 1-2-4.	Stand alone system (with external printer / slip printer)  Master/satellite system with external (local) printer  Master/satellite system with external (remote) printer  External printer DIP switch configuration	I-6 I-7
2. System do	own and recovery	I-9
2-1.Measure	s to prevent trouble	I-10
2-2.Master terminal failure		I-11
2-2-1-1. 2-2-1-2. 2-2-2. 2-2-2-1. 2-2-2-2.	Check tracking master terminal failure  Detection of check tracking master terminal failure  Master failure during check tracking operation  Remote printer failure  Detection of remote printer failure  Master printer failure during printing on remote printer  y processing	I-11 I-12 I-13 I-13
2-3-1. 2-3-2. 2-4.Master fa	Master/backup master down detection	I-14
2-5.Satellite	terminal down	I-14

To prevent malfunctions caused by the weak batteries, charge the memory protection batteries for over 12-hours before installation or after a longtime vacation (over 30 days).

- Before installation, initialize the terminal and leave it turn on over 12-hours.
- After a longtime vacation, initialize the terminal and restore the program data if the terminal is in malfunction, and leave it turn on over 12-hours.
- Over 48-hours charging makes the batteries fully charged.

This is a "Table of Contents preview" for quality assurance

The full manual can be purchased from our store:

https://the-checkout-tech.com/manuals/casio/QT-6100 installation and down recovery manuals/casio/QT-6100 installation and down recovery ma

And our free Online Keysheet maker:

https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/

HTTPS://THE-CHECKOUT-TECH.COM