

# SHARP PARTS GUIDE

## MODEL ER-2970

Table of destinations

SELECTION CODE	COUNTRIES
KA	Australia
KB	U. Kingdom
SA	Korea
SB	Saudi Arabia, U. S. of Brazil
SC	Formosa
SD	R. of Colombia, Costa Rica, Dominican, Republic, R. of Panama, R. of Guatemala, Honduras, Venezuela, Nicaragua, El Salvador
SE	Hong Kong
SF	Thailand
* SG	Kuwait, Cyprus, Lebanon, Bahrain, Thailand, Indonesia, Tahit, Pakistan, Iran, Syria, Turkey, Jordan, Iraq
SH	South Africa
SJ	Philippines
SL	New Zealand
SM	Kenya, Malta, UAE, Malaysia, Singapore
TQ	SEEG territory other than Germany
TS	Germany
RA1	Tunisia, West Africa
RA2	R. of Argentine, R. of Paraguay
RA3	Greece
RA4	R. of Chile, R. of Uruguay
RA5	Sri Lanka
RA6	Egypt
RA7	Curacao, Barbados (120V)
RA8	Liberia
RA9	R. of Peru
TR	Spain
SMT	Nigeria
RB1	U. S. of Brazil
RB2	Barbados (220V)
* RB3	Indonesia

Parts marked with " △ " is important for maintaining the safety of the set. Be sure to replace these parts with specified ones for maintaining the safety and performance of the set.

[Click here to download the full manual at THE-CHECKOUT-TECH.COM](http://THE-CHECKOUT-TECH.COM)