


SHARP PARTS GUIDE

CODE : 00ZUP3500UPGE



LEAD-FREE SOLDER MODEL

POS TERMINAL

MODEL UP-3500

(U version)

CONTENTS

- ① Display section
- ② Exteriors
- ③ Packing material & Accessories
- ④ Sub PWB unit
- ⑤ CPU PWB unit
- ⑥ LED PWB unit
- ⑦ T/P PWB unit
- ⑧ DC Jack PWB unit
- ⑨ Service tools

■ index

Parts marked with "△" are important for maintaining the safety of the set. be sure to replace these parts with specified ones for maintaining the safety and performance of the set.

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:

[https://the-checkout-tech.com/manuals/sharp/UP-3500 parts guide manual.html](https://the-checkout-tech.com/manuals/sharp/UP-3500%20parts%20guide%20manual.html)

And our free Online Keysheet maker:

<https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/>

[HTTPS://THE-CHECKOUT-TECH.COM](https://THE-CHECKOUT-TECH.COM)