


SHARP SERVICE MANUAL

CODE: 00ZXEA110VSME



XE-A110



XE-A130

ELECTRONIC CASH REGISTER

XE-A110 MODEL XE-A130

SRV KEY: Not necessary
PRINTER: M-31
(For "V" version)

CONTENTS

| | |
|---|----|
| CHAPTER 1. SPECIFICATIONS | 1 |
| CHAPTER 2. OPTIONS | 5 |
| CHAPTER 3. MASTER RESET AND PROGRAM RESET | 5 |
| CHAPTER 4. HARDWARE DESCRIPTION | 5 |
| CHAPTER 5. TEST FUNCTION | 9 |
| CHAPTER 6. SERVICE PRECAUTION | 11 |
| CHAPTER 7. CIRCUIT DIAGRAM AND PWB LAYOUT | 12 |
| PARTS GUIDE | |

Parts marked with "▲" is important for maintaining the safety of the set. Be sure to replace these parts with specified ones for maintaining the safety and performance of the set.

[Click here to download the full manual at THE-CHECKOUT-TECH.COM](http://THE-CHECKOUT-TECH.COM)