

GSE

Model 355, 465 and 562 Check Weighers



Users Guide

Version 1.0



Table of Contents

CHAPTER 1: INTRODUCTION	1
SPECIFICATIONS	1
CHAPTER 2: INSTALLATION.....	3
OUT OF BOX SETUP	3
STACK LIGHT OPTION INSTALLATION	3
<i>Model 355 Installation</i>	4
<i>Wiring the Stack Light</i>	6
<i>Model 465 Installation</i>	7
<i>Model 562 Installation</i>	9
CHAPTER 3: MODEL 355 SETUP	11
INTRODUCTION.....	11
<i>Display</i>	11
<i>Keypad</i>	12
CHECKWEIGHING METHOD EXAMPLES	12
SETUP	16
<i>Access Checkweighing Methods</i>	16
<i>Enter Target and Limits in the Setup Mode</i>	16
<i>Save the Changes</i>	16
<i>Enter Target Value and Limits From the Weigh Mode</i>	17
PARTS COUNTING.....	17
<i>Enable Count Mode (Quantity)</i>	18
<i>Save the Changes</i>	18
<i>Counting Methods</i>	18
CHAPTER 4: MODEL 465 SETUP	19
<i>Display</i>	19
<i>Keypad</i>	19
CHECKWEIGHING METHOD CHOICES.....	20
<i>Fixed Limit</i>	20
<i>% of Targ</i>	20
STATUS INDICATION	21
OPERATING MODE CHOICES.....	22
<i>NET MODE</i>	22
<i>GROSS MODE</i>	22
<i>COUNT MODE</i>	22
SETUP (F1)	23
<i>View Method and Operating Mode</i>	23

<i>Set Method and Operating Mode</i>	23
SET TARGET AND LIMITS (TARGET)	24
<i>Enter a Known Target Value</i>	24
SET A PASSWORD CODE	25
PRODUCT ID	25
<i>Quick Recall by ID Number:</i>	25
<i>Recall by Product ID or Product Name:</i>	26
CHAPTER 5: MODEL 562 SETUP	27
DISPLAY	27
KEYPAD	27
PARAMETER MAP	28
SET TARGET (F1)	29
<i>Enter a Known Target Value</i>	29
SETUP MODE (F2)	30
<i>Operating Mode (1)</i>	30
<i>Over / Under Target (2)</i>	32
<i>Display Style (3)</i>	33
<i>Based On (4)</i>	34
PRODUCT ID (F3)	35
<i>Access an Existing Product ID</i>	36
SET TARGET OR UNDER/OVER LIMITS	37
SET A PASSWORD CODE	37
CHAPTER 6: CALIBRATION	39
MODEL 355 CHECKWEIGHER	39
<i>Access Calibration</i>	39
<i>Performing Calibration</i>	39
<i>Establishing Zero</i>	39
<i>First Zero</i>	40
<i>Last Zero</i>	40
<i>False Zero</i>	41
<i>Only Zero</i>	42
<i>Reset Calibration</i>	43
<i>Exiting Calibration</i>	44
MODEL 465 AND 562 CHECKWEIGHER	46
<i>Performing Calibration</i>	46
<i>Establishing Zero</i>	46
<i>New Zero</i>	46
<i>Last Zero</i>	47
<i>Temp Zero?</i>	48
<i>Only Zero?</i>	48
<i>Cal Reset</i>	49
<i>Exiting Calibration</i>	50

CHAPTER 7: ERROR CODES	51
MODEL 355	51
MODEL 465 AND 562.....	55

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:

[https://the-checkout-tech.com/manuals/GSE/355 and 465 and 562 Check Weighers user](https://the-checkout-tech.com/manuals/GSE/355%20and%20465%20and%20562%20Check%20Weighers%20user%20manual.pdf)

And our free Online Keysheet maker:

<https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/>

[HTTPS://THE-CHECKOUT-TECH.COM](https://the-checkout-tech.com)