

P2000B / P2000BS Indicator

Technical Manual

CE



Contents

1. Main Data	1
2. Main Features	1
3. Construction	2
4. Operation Keys Instruction	4
5. Use	5
5.1. Preparation	5
5.2. Power-on operation	5
5.3. Zero-setting	6
5.4. Deducting tare	6
5.5. Accumulation	6
5.6. Display converting for gross weight and net weight	8
5.7. RS-232C output	8
5.8. Ticket printing output	9
5.9. Unit switch	10
5.10. Digit Input	11
6. Use Guide	11
7. Data Setting and Calibration	12
7.1. Entering main directories	13
7.2. Entering subdirectories	13
7.3. Calibration	15
7.4. Flow chart for setting and calibraton	18

Notice to Users

You are welcome to use Pioneer series indicators. This indicator possesses such features as fashionable appearance, cordial operation-interface, high-resolution, reliable measuring performance and so on. Please read this manual carefully before you operate the indicator so that you might fully enjoy the convenience from it. We reserve the right to make amendments to the specifications of our products.

Note: Both HST and Pioneer are the registered trade marks of our company.

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:

[https://the-checkout-tech.com/manuals/HST/P2000B P2000BS technical manual.html](https://the-checkout-tech.com/manuals/HST/P2000B_P2000BS_technical_manual.html)

And our free Online Keysheet maker:

<https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/>

[HTTPS://THE-CHECKOUT-TECH.COM](https://THE-CHECKOUT-TECH.COM)