


SMART WEIGHING SOLUTIONS



rinstrum

**X320 IP69K
Digital Indicator
Operator Manual**

Table of Contents

1. INTRODUCTION.....	2
1.1. Approvals	2
1.2. Features	2
1.3. Manuals	2
2. SAFETY	3
2.1. Operating Environment	3
2.2. Electrical Safety.....	3
2.3. Cleaning	3
3. BASIC OPERATION.....	4
3.1. User Interface Display and Controls	4
3.2. Operation Keys.....	5
3.3. Stability Considerations.....	7
3.4. Annunciators	8
4. BASIC WEIGHING.....	9
4.1. Normal Weighing.....	9
4.2. Using Tare.....	9
5. SPECIAL FUNCTIONS.....	10
5.1. Testing the Display.....	10
5.2. Counting	10
5.3. Units Switching (kg / lb).....	10
5.4. Hold	11
5.5. Peak Hold.....	11
5.6. Live Weighing.....	12
5.7. Showing Totals	13
5.8. High Resolution (K304, K306).....	13
5.9. High Resolution (K303)	14
5.10. Automatic Tare	14
5.11. Check Weigh.....	15
6. ERROR MESSAGES.....	16
6.1. Weighing Errors.....	16
6.2. Setup and Calibration Errors	17
6.3. Diagnostic Errors	18

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:

https://the-checkout-tech.com/manuals/rinstrum/X-320_IP69K_Indicator_operator_manual.pdf

And our free Online Keysheet maker:

<https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/>

[HTTPS://THE-CHECKOUT-TECH.COM](https://THE-CHECKOUT-TECH.COM)