

XK3190-C601

WEIGHING INDICATOR

(BATCHING VERSION)

MANUAL

PLEASE READ THIS MANUAL VERY CAREFULLY
BEFORE OPERATING

Dec 2006

Specifications subject to change without prior notice

CONTENTS

1. GETTING STARTED
2. TECHNICAL PARAMETERS AND SPECIFICATIONS
3. LAYOUT AT FRONT AND DESCRIPTION
4. Parameter Setting and Calibration
5. INSTRUCTION FOR OPERATION
6. OPERATION ERROR CODES
7. APPENDIX

1. GETTING STARTED

CAUTION

- *This is not a toy. Keep out of reach of children;*
- *This indicator is not an explosion proof device;*
- *This indicator is not a water proof device;*
- *Do not open this indicator, no user serviceable parts inside. Always contact supplier for service.*

1.1 Introduction

XK3190-C601 weighing indicator (batching version) adopts MCS-51 SCM and high speed $\Sigma - \Delta$ A/D conversion method with max.100 times/s conversion speed. It can make up batching scale with load cell and other mechanical parts, applied in high speed and high precision weighing control occasion.

1.2 Features

- Calibration and operation all by panel keys;
- With parallel printing interface connected to stylus printer;
- Able to print out weighing records, accumulation value and formula;
- Able to save/check/delete weighing records, data protection at sudden power failure;
- With real clock, calendar;
- Able to set zero tracking range and auto/manual zero range;
- Able to set A/D conversion speed and digital

This is a “Table of Contents preview” for quality assurance

The full manual can be found at <http://the-checkout-tech.com/estore/catalog/>

We also offer free downloads, a free keyboard layout designer, cable diagrams, free help and support.

<http://the-checkout-tech.com> : *the biggest supplier of cash register and scale manuals on the net*