

XK3190-C8

Weighing Indicator

User Manual

Version April 2009

Manufactured by Shanghai Yaohua Weighing System Co., Ltd.

XK3190-C8

Contents

Chapter 1 Profile	2
Chapter 2 Main Parameters	3
Chapter 3 Installation, Interface and Data Format	4
I. Diagram of Front and Back Function Buttons of Indicator	4
II. Connection of Load Cell and Indicator	6
III. Input and Output Interface	6
IV. Large-screen Display Interface	6
V. Serial Communication Interface	6
VI. Analog output	7
VII. Print and Storage	8
Chapter 4 Parameter Setting and Calibration	9
I. [SEt 0] Enquiry Parameter	9
II. 【SEt 1】 General Parameters	11
III. [SEt 2] Control Parameters	12
IV. Record Print [SEt 3]	16
V. Calibration	16
Chapter 5 Operating Instructions	18
I. Startup and zero setting upon startup	18
II. Zero setting manually	18
III. Tare	18
IV. Setting of date and time	18
V. Startup/stop	18
VI. Peak holding	18
VII. Input and output function	18
VIII. Inquiry of common parameters	19
Chapter 6 Explanations of Control Procedure	20
I. Mode 0 (additive mode with 1 batching material)	20
II. Mode 1 (subtracting mode of 1 batching material)	21
III. Mode 2 (additive scale for two materials)	24
IV. Mode 3 (catchweighing mode)	25
Annex 1 Error Message Prompt	29
Annex 2 Large Screen Data Waveform Diagram and Format	30
Annex 3 Serial Communication – Data Format of Command Response Mode	32

Dear customer:

Please read carefully the user manual before using the indicator!

This is a “Table of Contents preview” for quality assurance

The full manual can be found at <http://the-checkout-tech.com/estore/catalog/>

We also offer free downloads, a free keyboard layout designer, cable diagrams, free help and support.

<http://the-checkout-tech.com> : *the biggest supplier of cash register and scale manuals on the net*