# XK3190-D10

## WEIGHING INDICATOR

## MANUAL

PLEASE READ THIS MANUAL VERY CAREFULLY BEFORE USE

### CONTENTS

- 1. GETTING STARTED
- 2. TECHNICAL PARAMETERS AND SPECIFICATIONS
- 3. LAYOUT AT FRONT AND BACK
- 4. Connecting to Other Devices
- 5. Calibration and password setting
- 6. Operation
- 7. Save and print
- 8. CODE DISPLAY

#### APPENDIX

### 1. GETTING STARTED

#### CAUTION

- This is not a toy. Keep out of reach of children;
- This indicator is not an explosion proof device;
- This indicator is not a water proof device;
- Do not open this indicator, no user serviceable parts inside.
  Always contact supplier for service.

#### 1.1 Introduction

Weighing indicator XK3190-D10 adopts high precision  $\Sigma$ - $\Delta$  A/D conversion technology, widely applied in electronic floor scale, electronic truck scale, static railroad truck scale and so on alike static weighing system equipped with 1~8 load cell.

#### 1.2 Features

- Good consistency, no need to re-calibrate a scale if change the former indicator, just input the recorded former calibration parameter is OK
- Software on-line update and modification locally or by ISP
- Printing content and format user-defined
- Aluminum alloy housing with strong anti-disturbance ability, ESD method for printer and communication interface
- Password settable for operation of parameter setting, record check, record clear;
- Password revisable for time power off function

This is a "Table of Contents preview" for quality assurance

The full manual can be purchased from our store:

https://the-checkout-tech.com/manuals/Yaohua/XK3190-D10 operation manual.html

And our free Online Keysheet maker:

https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/

HTTPS://THE-CHECKOUT-TECH.COM