



PULSAR C
CCD SCANNER
Configuration Manual



Metrologic Instruments GmbH
Dornier Strasse 2
82178 Puchheim
Germany
Tel +49 89 890190
Fax +49 89 89019200
www.europe.metrologic.com

Table of Contents

Restore Default Settings 1
Exit Setup without Changes 1
Configure Through RS232 1
List Setting 1
Buzzer Settings 2
Reading Redundancy Setting 2
Scan Mode Setting 3
Scanner Time-out Duration 3
Negative Barcode Setting 3
Delay between Reread 4
Keyboard Wedge Parameters 4
RS-232 Parameters 8
Prefix / Postfix Settings 10
Character Substitution 10
Code ID Selection 10
Code ID Setting 11
Length Code Setting (2 digits) 12
Select Readable Codes 15
Code39 Parameters 19
Italy Pharmacode Parameters 19
French Pharmacode Parameters 20
Industrial 25 Parameters 20
Interleave 25 Parameters 21
Matrix 25 Parameters 23
Codabar Parameters 24
Plessey Parameters 25
MSI Parameters 26
EAN128 Parameters 27
EAN8 Parameters 28
UPCA Parameters 28
UPCE Parameters 29
EAN13 Parameters 30
Activate Editing Formats 31
Editing Format Parameters 32
Decimal Digits 44
Hexadecimal Digits 45
Key Type 46
Key Status 46
KBD Wedge Character Table 47
RS-232 Character Table 47

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:

[https://the-checkout-tech.com/manuals/Metrologic/MS6220 Pulsar C configuration manu](https://the-checkout-tech.com/manuals/Metrologic/MS6220%20Pulsar%20C%20configuration%20manual.pdf)

And our free Online Keysheet maker:

<https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/>

[HTTPS://THE-CHECKOUT-TECH.COM](https://the-checkout-tech.com)