



**SHARP**

**SERVICE MANUAL**

**MODEL ER-2000U**

**ELECTRONIC CASH REGISTER**

**SHARP CORPORATION**



## TABLE OF CONTENTS

	Page
1. Introduction . . . . .	1
2. Explanations in general . . . . .	2
2-1. Key layout . . . . .	2
2-2. Specifications of each key . . . . .	3
2-3. General specifications . . . . .	4
2-4. Major operations illustrated . . . . .	5
3. Specifications in detail . . . . .	9
3-1. Printing format . . . . .	9
3-2. Others . . . . .	11
3-3. Operation exemplified . . . . .	13
3-4. Occurrence of errors . . . . .	15
4. All about circuits . . . . .	17
4-1. Block diagram . . . . .	17
4-2. Display circuit . . . . .	18
4-3. Type drum driving circuit . . . . .	18
4-4. Stamping circuit . . . . .	19
4-5. Detail tape take-up . . . . .	19
4-6. Power failure detecting signal . . . . .	21
4-7. Protective circuits . . . . .	22
4-8. Drawer unit . . . . .	23
4-9. Key-locked sections . . . . .	23
4-10. Resetting counter . . . . .	24
4-11. Printer motor signal $\overline{\text{MOT}}$ . . . . .	24
5. Service . . . . .	25
5-1. Repair methods . . . . .	25
5-2. Supply of consumable parts . . . . .	26
5-3. Stamp unit . . . . .	27
5-4. Cautions (Antistatic measures; revised specifications) . . . . .	28
6. Parts guide . . . . .	
7. Circuit diagrams & Part/signal layout charts . . . . .	
7-1. Part/signal layout chart of operation unit PWB . . . . .	
7-2. Operation unit circuitry . . . . .	
7-3. Part/signal layout chart of power source PWB . . . . .	
7-4. Part/signal layout chart of display unit PWB . . . . .	
7-5. Power source circuitry . . . . .	
7-6. Key block circuitry . . . . .	
7-7. Printer wiring diagram . . . . .	

[Click here to download the full manual at THE-CHECKOUT-TECH.COM](http://THE-CHECKOUT-TECH.COM)