


SHARP SERVICE MANUAL

CODE : 00ZERA770VSME



MODEL ER-A770

(For "V" version)

CONTENTS

| | |
|--|-------|
| CHAPTER 1. SPECIFICATIONS | 1 - 1 |
| CHAPTER 2. OPTIONS | 2 - 1 |
| CHAPTER 3. SERVICE PRECAUTION | 3 - 1 |
| CHAPTER 4. SRV RESET (Program Loop Reset) and switch to SRV mode ... | 4 - 1 |
| CHAPTER 5. MASTER RESET | 5 - 1 |
| CHAPTER 6. DIAGNOSTICS SPECIFICATIONS..... | 6 - 1 |
| CHAPTER 7. CIRCUIT DESCRIPTION | 7 - 1 |
| CHAPTER 8. CIRCUIT DIAGRAM | 8 - 1 |
| CHAPTER 9. PWB LAYOUT | 9 - 1 |
| PARTS GUIDE | |

Parts marked with "⚠" are important for maintaining the safety of the set. Be sure to replace these parts with specified ones for maintaining the safety and performance of the set.

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:

[https://the-checkout-tech.com/manuals/sharp/ER-A770 service manual.html](https://the-checkout-tech.com/manuals/sharp/ER-A770%20service%20manual.html)

And our free Online Keysheet maker:

<https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/>

[HTTPS://THE-CHECKOUT-TECH.COM](https://THE-CHECKOUT-TECH.COM)