
SHARP

SERVICE MANUAL

CODE: 00ZM42IISM///E



PRINTER M-42 I

(Ki-OB0092CCZZ)

The M-42 II printer is a high speed version of the M-42 printer. As this manual supplements what the M-42 II printer differs from the M-42 printer, refer to the M-42 printer Service Manual for details of mechanisms and operational theory.

1. What the M-42II printer specification differs from those of the M-42 printer.

Printing speed (Average speed at 6.0V DC)

	M-42II	M-42
19 columns	Approx. 0.9 line/sec	Approx. 0.8 line/sec
7 columns	Approx. 2.2 line/sec	Approx, 1.9 line/sec

2. Components used for the M-42II only (items not interchangeable with those of the M-42)

Parts name	Difference	
(Frame)	Addition of guide shaft hole change in the detection assy installation location	
Motor gear	25% faster printing speed with a change in the gear ratio	
Print changeover cam		
Selecting gear assy	Bounce preventive measures due to increased printing speed	
Selecting ratchet		
(Trigger yoke)	On the same body with the select gear assy, for better assembly efficiency	
Carriage assy	Use of the new type due to addition of the guide shaft	
Guide shaft	New type used	
Detection assy	Change in the installation location due to the addition of the guide shaft	
(Paper holding spring)	Structural change in the frame and increased load	

3. Components in common use with the M-42

Parts name	Difference	
Platen assy	0.5 mm wider printing area	
Carriage stopper Stopper plate	Common use with the M-42 and for better assembly efficiency	
Hammer	Structural change in the spring hook portion	
Hammer return spring	Structural change	0-WV-0 → 0-WV-0

This is a "Table of Contents preview" for quality assurance

The full manual can be purchased from our store:

https://the-checkout-tech.com/manuals/sharp/M-42II internal printer service manual.html

And our free Online Keysheet maker:

https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/

HTTPS://THE-CHECKOUT-TECH.COM