

INTERFACE BOARD INSTALLATION INSTRUCTIONS

REF.# 62100 LX IF7-1 K-UNIT

#OP-049-001

Ref. #	Parts Name	Qty	Remarks
40527	IF UNIT 071-1	1	interface board
40633	RT UNIT 101-4	2	ch-D and E: consists of 9-pin D-sub connector with cable connector and 2 hexagonal screws
33013	B(M3X8)	3	to fix interface board on the lower case (three screws are used for very early production)
34180	LOCKING SPACER WLS-12-0	1	to support interface board (not used if a spacer already mounted for very early production)

Prepare an insulating tape to fix cables.

How to Install Interface Board

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:

[https://the-checkout-tech.com/manuals/uniwell/IF-7 Interface board installation manual.h](https://the-checkout-tech.com/manuals/uniwell/IF-7%20Interface%20board%20installation%20manual.h)

And our free Online Keysheet maker:

<https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/>

[HTTPS://THE-CHECKOUT-TECH.COM](https://the-checkout-tech.com)