

Table of Contents

	Page
General Notes	2
Calibration Procedure	3
Cover Removal and Installation	4
Main/Display Board Removal and Installation	4
Customer Display Board Removal and Installation	4
A/D Board Removal and Installation	5
Load Cell Assembly Removal and Installation	5
Battery Removal and Installation	5
Parts List	6
Exploded View Drawing	7

BERKEL INCORPORATED
One Berkel Drive LaPorte, Indiana 46350-2594
219/326-7000 Fax 219/324-2928
(800) 348-0251

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:

[https://the-checkout-tech.com/manuals/avery berkel/CZ-342 installation and calibration m](https://the-checkout-tech.com/manuals/avery%20berkel/CZ-342%20installation%20and%20calibration%20manual.pdf)

And our free Online Keysheet maker:

<https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/>

[HTTPS://THE-CHECKOUT-TECH.COM](https://THE-CHECKOUT-TECH.COM)