


SMART WEIGHING SOLUTIONS



rinstrum

1203

Display Manual

For use with Software Versions 1.0 and above

Table of Contents

1.	INTRODUCTION.....	4
1.1.	1203 Features	4
1.2.	1203 Manuals	4
1.3.	Document Conventions	4
2.	INSTALLATION	5
2.1.	Warnings	5
2.2.	Installation Procedure	5
2.3.	Failures and Solutions	5
3.	BASIC OPERATION	6
3.1.	User Interface Display and Controls	6
3.1.1.	Display	6
3.1.2.	Annunciators	6
3.1.3.	Control Keys	7
3.2.	Reading Types.....	9
3.3.	Data Entry.....	9
3.3.1.	Numeric Entry	9
3.3.2.	Selections and Options	9
3.4.	Basic Weighing Terminology	10
4.	DIGITAL SETUP	11
4.1.	Accessing Setup Mode	11
4.2.	Setup Mode (Saving Changes and Exiting)	11
4.3.	Passcode	11
4.4.	Instrument Setup	12
5.	APPENDIX A: CALIBRATION.....	21
5.1.	Introduction and Warnings.....	21
5.2.	Digital Calibration: Zero Calibration Routine	21
5.3.	Digital Calibration: Span Calibration Routine	21
5.4.	Direct mV/V Calibration: Zero Calibration Routine.....	21
5.5.	Direct mV/V Calibration: Span Calibration Routine.....	22
6.	APPENDIX B: SETPOINTS	23
6.1.	Introduction	23
6.2.	Operation	23
6.2.1.	Example 1: Control Level of Product in 2000kg Tank	24
6.2.2.	Example 2: Control Weighing of Product Out of Silo into 100kg Drums	24
7.	APPENDIX C: GENERAL.....	25
7.1.	Data Entry	25
7.1.1.	Numeric Entry - Example	25
7.1.2.	Selections and Options - Example	25
7.2.	Commands	25
7.3.	ASCII Codes	26
7.4.	Scale Build: Identification.....	27
7.5.	Formats - Communication Ports	28
7.6.	Remote Input - Options.....	30
7.7.	List of Reading Types (Data Types)	31
7.8.	Error Codes	32
7.9.	Glossary of Terms	33
7.10.	List of Figures	33
8.	INDEX.....	34

This is a “Table of Contents preview” for quality assurance

The full manual can be found at <http://the-checkout-tech.com/estore/catalog/>

We also offer free downloads, a free keyboard layout designer, cable diagrams, free help and support.

<http://the-checkout-tech.com> : the biggest supplier of cash register and scale manuals on the net