

SMART WEIGHING SOLUTIONS



**rinstrum**

**400 Series**

**(K411)**

**Batching Indicator  
Quick Start Manual**

# Table of Contents

<b>1. INTRODUCTION</b> .....	<b>3</b>
1.1. Manuals .....	3
1.2. Shipping Contents .....	3
<b>2. SPECIFICATIONS</b> .....	<b>4</b>
<b>3. INSTALLATION</b> .....	<b>5</b>
3.1. Introduction .....	5
3.2. General Warnings.....	5
3.3. Panel Mount Template .....	6
3.4. Function Keys .....	6
3.5. Optical Communications .....	6
<b>4. CONNECTIONS</b> .....	<b>7</b>
4.1. Cable Connections .....	7
4.2. DC Power (DC PWR +, DC PWR –) .....	7
4.3. Load Cell Connection .....	7
4.4. Auxiliary Connections .....	9
4.5. Connecting Shields.....	11
4.6. Legal Sealing Details.....	12
<b>5. INSTRUMENT SETUP</b> .....	<b>15</b>
5.1. Accessing Full/Safe Setup .....	15
5.2. Exiting Full or Safe Setup .....	16
5.3. Using Menus.....	16
<b>6. SETUP MENUS</b> .....	<b>17</b>
6.1. GEN.OPT (General options) .....	17
6.2. H.WARE (Hardware Configuration & Test) .....	20
6.3. SCALE (Loadcell options and calibration).....	23
6.4. FUNC (Special functions).....	26
6.5. SER.NET (Network communications) .....	30
6.6. SER.AUT (Automatic transmit).....	31
6.7. PRINT (Printouts) .....	32
6.8. SETP (Setpoints).....	34
6.9. BATCH.....	36
6.10. ANL.OUT (Analogue Output) .....	44
6.11. End (Save and exit) .....	44
<b>7. ACCESSORY MODULES</b> .....	<b>45</b>
7.1. General .....	45
7.2. Installation and configuration.....	45
7.3. Input/Output Configuration .....	46

**Quick Start - Software Version 1.2x**

---

- These setup menus are discussed further in 0 .....47
- 7.4. BATCH page 36 and 6.7 PRINT (Printouts).....48
- 7.5. Analogue Output.....50
- 7.6. Communications .....51
- 8. HARDWARE TESTING .....52**
  - 8.1. Overview.....52
  - 8.2. Check Hardware Allocation .....52
  - 8.3. Check Inputs.....53
  - 8.4. Force Outputs .....53
  - 8.5. Force Analogue Output .....54
  - 8.6. Check Load Cell Hardware .....54
- 9. ERROR MESSAGES.....55**
  - 9.1. Overview.....55
  - 9.2. Weighing Errors .....55
  - 9.3. Setup Errors .....56
  - 9.4. Calibration Errors.....57
  - 9.5. Pause Conditions .....58
  - 9.6. Diagnostic Errors .....59

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:

[https://the-checkout-tech.com/manuals/rinstrum/R400 quick start manual.html](https://the-checkout-tech.com/manuals/rinstrum/R400%20quick%20start%20manual.html)

And our free Online Keysheet maker:

<https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/>

[HTTPS://THE-CHECKOUT-TECH.COM](https://THE-CHECKOUT-TECH.COM)