



***Model S610 Digital  
Counting Scale***

**Set-Up Manual**

Revision 1.0  
July, 2003

Contents subject to change without notice.

Salter Brecknell Weighing Products.  
1000 Armstrong Drive  
Fairmont, MN 56031  
Tel (800) 637-0529  
Tel (507) 238-8702  
Fax (507) 238-8271

E-mail: [sales@salterbrecknell.com](mailto:sales@salterbrecknell.com)

Web: [www.salterbrecknell.com](http://www.salterbrecknell.com)

**TABLE OF CONTENTS**

	<u>Page</u>
Chapter 1: Introduction To The S610 Series Setup Manual .....	1-1
Chapter 2: Installation .....	2-1
2.1 Overview.....	2-1
2.1.1 Connecting the serial printer, remote display or computer.....	2-1
2.1.2 Connecting the power supply .....	2-1
Chapter 3: Configuration .....	3-1
3.1 Configuration Overview .....	3-1
3.2 Setup (“F”) Menu .....	3-1
3.2.1 Entering the Setup Menu.....	3-1
3.2.2 Navigating in the Setup Menu .....	3-1
3.2.3 Notes on the Setup Menu.....	3-2
3.2.4 Exiting the Setup Menu .....	3-2
3.3 User (“A”) Menu.....	3-2
Chapter 4: Setup Menu Descriptions and Procedures.....	4-1
4.1 Setup Menu Descriptions .....	4-1
4.2 Resetting Factory Defaults .....	4-2
Chapter 5: User Menu Descriptions and Procedures.....	5-1
5.1 User Menu Descriptions .....	5-1
Chapter 6: Calibration .....	6-1
6.1 Calibration Overview .....	6-1
6.2 Zero Calibration (F16) .....	6-1
6.3 Span Calibration (F17) .....	6-1

## LIST OF FIGURES

2-1 S610 Rear Panel.....	2-1
3-1 Setup Menu Key Assignments .....	3-1
3-2 Setup Menu Chart .....	3-2
3-3 User Menu Key Assignments.....	3-5

## LIST OF TABLES

4-1 Factory Restore Key.....	4-2
------------------------------	-----

This is a “Table of Contents preview” for quality assurance

The full manual can be found at <http://the-checkout-tech.com/estore/catalog/>

We also offer free downloads, a free keyboard layout designer, cable diagrams, free help and support.

<http://the-checkout-tech.com> : *the biggest supplier of cash register and scale manuals on the net*