

W10 DIGITAL WEIGHING INDICATOR

OPERATION MANUAL

PLEASE READ THIS MANUAL VERY CAREFULLY BEFORE ATTEMPT TO OPERATE
THE SCALE

DECEMBER 2001

Specifications subject to change without prior notice

CONTENTS

1. Introduction
2. Cautions
 - 2.1 Warning
 - 2.2 Power Supply
3. Specifications
4. Installation
 - 4.1 Unpack the unit
 - 4.2 Installation Procedures
 - 4.3 Load Cell Connection
5. Operation Panel
 - 5.1 Front Side Illustration
 - 5.2 Back Side Illustration
6. Setting
 - 6.1 Setting Basic Parameters
 - 6.2 Setting Capacity
 - 6.3 Calibration
 - 6.4 Password Setup
7. Troubleshooting
 - 7.1 Zero Calibration
 - 7.2 Span Calibration
8. Outputs
9. Care and Maintenance

This is a “Table of Contents preview” for quality assurance

The full manual can be found at <http://the-checkout-tech.com/estore/catalog/>

We also offer free downloads, a free keyboard layout designer, cable diagrams, free help and support.

<http://the-checkout-tech.com> : *the biggest supplier of cash register and scale manuals on the net*