




WI-105 Indicator User's Manual

Table of Contents

Table of Contents.....	3
Specifications	4
Introduction.....	5
Installation	5
Overall dimensions.....	5
Panel cut-out.....	5
Fastening clips	5
Front Panel.....	6
Weighing Operations	7
Zeroing the Indicator	7
Performing a Simple Gross Weighment.....	7
Performing a Single Tare Weighment.....	8
Performing a Multiple Tare Weighment	9
Cancelling a Tare.....	10
Printing Data.....	10
Error Message.....	11
Setting up the Trip Values (option)	11
Peak or Valley Hold Function (optional)	13



Warning

To avoid the possibility of electric shock or damage to the instrument, always switch off the instrument and isolate from the power supply before carrying out any routine maintenance.

This instrument may only be used when housed within another enclosure, e.g. rack, panel or other housing. Full electrical safety requirements (note: high voltages within instrument) will only be met

by enclosure in a suitable housing.

Cleaning the front panel

Switch the instrument off and isolate it from the power supply. The front panel may only be cleaned with a slightly damp (water only) clean cloth. Ensure that no water gets inside the unit.

This is a “Table of Contents preview” for quality assurance

The full manual can be purchased from our store:

[https://the-checkout-tech.com/manuals/Weigh-Tronix/WI-105 user manual.html](https://the-checkout-tech.com/manuals/Weigh-Tronix/WI-105%20user%20manual.html)

And our free Online Keysheet maker:

<https://the-checkout-tech.com/Cash-Register-Keysheet-Creator/>

[HTTPS://THE-CHECKOUT-TECH.COM](https://THE-CHECKOUT-TECH.COM)