

XK3190-C601

WEIGHING INDICATOR

(DISPENSING VERSION)

USER MANUAL

content

Chapter I General -----3

Chapter II Main parameter-----4

Chapter III Installation, interface and data format-----5

1. Front view and back view
2. Load cell connection with indicator
3. Printer connection with indicator
4. Scoreboard connection
5. Serial communication interface
6. control interface

Chapter IV Parameter setting and calibration-----14

1. Parameter setting
2. Calibration

Chapter V Operation-----22

1. Start and ZERO setting upon start
2. manual ZERO setting
3. Tare
4. Date and Time
5. Printing
6. Data check and delete
7. Start/stop

**Chapter VI Dispensing scale application and example
-----24**

Appendix: -----27

1. Error information
2. Question and answer

Dear user,

Please read the user manual carefully before operation

This is a “Table of Contents preview” for quality assurance

The full manual can be found at <http://the-checkout-tech.com/estore/catalog/>

We also offer free downloads, a free keyboard layout designer, cable diagrams, free help and support.

<http://the-checkout-tech.com> : *the biggest supplier of cash register and scale manuals on the net*